



Navy Blue HRGB

Plain Water Solubility	100
50GPL Salt Solubility	40
Stability at 30°C	30 Min.
Exhaust Dyeing	Suitable
Cold-Pad-Batch	Suitable
Printing	Suitable

FASTNESS										
Light Fastness (Xenon ARC Lamp)			1/1		1/3		1/6		1/12	1/25
			3-4		3		3		3	2-3
Washing Fastness Multifiber Staining at 160°C	CS	CTA	CA	CO	PA	PES	PAN	CV	WOOL	
	5	5	-	4-5	5	5	5	5	-	
Perspiration (Acidic) (Alkaline)					5					
					5					
Water, Severe					5					
Rubbing Fastness	DRY		WET		Dischargeability : Dischargeable					
	4-5		3							
Cl₂ Water (20PPM Active Chlorine)		3-4								